

FIGURE 1




FIGURE 1A




FIGURE 2




FIGURE 2B




FIGURE 2A




FIGURE 2C








FIGURE 2D

668101 9802450



0420086-101899

668101-98002450

APPROVED	BY	TAFTSMAN
O.G. FIG.	CLASS	SUBC.




FIGURE 3A




FIGURE 3





FIGURE 2B






FIGURE 5




FIGURE 5B




FIGURE 5C




FIGURE 5A




FIGURE 6  
(PRIOR ART)




FIGURE 6A




FIGURE 7

09420086-101899




FIGURE 7A




FIGURE 7B




FIGURE 8

09420086-101899

APPROVED	O.G. FIG.	
BY	CLASS	SUBC
DAFTMAN		




FIGURE 8E




FIGURE 8F

668T01" 98002460




FIGURE 8A




FIGURE 8B




FIGURE 8C




FIGURE 8D

0420086-10189